HNC-60AY Series Hall Current Sensor


Introduction


HNC-60AY Series Hall current transducer is the new generation product based on Hall effect. It is able to measure DC, AC, pulse and other currents with irregular waves under the condition of electrical isolation.


△Electrical Parameters (Ta=25°C)

AEICCUICAI I AI AII	icici s (1a 23 C)	,		
Туре		IDIC 25 IV	IDIC 1011	IDIC SOAM	IDIC COAN
Parameters	Symbols	HNC-25AY	HNC-40AY	HNC-50AY	HNC-60AY
Nominal measuring current	I_{PN}	±25A	±40A	±50A	±60A
Linear range	I_P	0~±50A	0~±60A	0~±75A	0~±100A
Nominal output voltage	V_{SN}	$\pm 4\mathrm{V} \pm 0.04\mathrm{V}(\mathrm{R_L} = 10\mathrm{K}\;\Omega\;)$			
Zero offset voltage	Vo	≤±40 mV			
Temperature drift of bridge offset	V _{OT}	≤±1 mV/°C			
Linear error	$\xi_{ m L}$	±0.5%			
Response time	Tr	≪3 μ S			
Supply voltage	Vc	±15V±5%			
Isolation voltage	V _d	2.0KV/50 or 60H _Z /1min			
Power dissipation current	I_{C}	(15+Ip/1200) mA			
Frequency bandwidth	f	DC~100KH _Z (-3dB)			
Operating temperature	Та	-25°C∼+85°C			
Storage temperature	Ts	-40 °C~+90 °C			

\triangle Dimension: (mm)









Features:

- ◆ Use close-loop current transducer based on Hall effect
- ◆ Adopt UL94V-0-recognized insulated casing
- ◆Output voltage signal
- ◆Low temperature drift
- ◆Wide frequency bandwidth
- ◆ High immunity against external disturbance

Applications:

- ◆ AC variable-frequency speed control system and servo motor
- ◆Uninterruptible power suppers (UPS)
- ◆ Switched-mode power supply
- ◆ Power supply for electric welding machine
- ◆Battery supply

Instructions for Use:

- ◆Connect the wire of transducer in correct way as required.
- ◆Inputting measured current from input end of transducer, the in-phase voltage signal can be obtained from output end by sampling.

Pin arrangement:

- ♦1: -Vc (-15V)
- **♦**2: 0V
- **♦**3: +Vc (+15V)
- ♦4: Output
- ♦5: primary In
- ♦6: primary Out